



Chemical Sector

2019

## Replace DN2000 stainless steel dome

- Cut off and reinstall stainless steel dome for filter replacement
- No chamber possible: Arc welding

- DN2000 and DN 500 (stainless, 10 mm thick)
- Full penetration arc welding
- 100% volume control
- 2 x 8-hour shifts over 4 days